

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:					
Company	Jay Marshall Resident Agent				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0070013		
Inspection Type:	COMPLETE		
Inspection Date:	Friday, October 08, 2004		
Start Date/Time:	10/8/2004 9:00:00 AM		
End Date/Time:	10/8/2004 1:00:00 PM		
Last Inspection:	Thursday, July 15, 2004		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Sunny, Temp 65 Deg F InspectionID Report Number: 425

> Accepted by: pgrubaug 10/29/2004

Permitee: UTAHAMERICAN ENERGY INC Operator: UTAHAMERICAN ENERGY INC

Site: HORSE CANYON MINE

Address: PO BOX 986, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	6,032.07	
Total Disturbed	122.49	
Phase I	61.65	
Phase II		
Phase III	Phase III	

Mineral Ownership

Types of Operations ✓ Federal **✓** Underground ✓ State Surface County **✓** Loadout Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permitting actions: Permit application for Lila Canyon is under review by the Division.

Inspector's Signature

Date

Friday, October 08, 2004

Karl Houskeeper, Environmental Scientist III Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070013 Inspection Type: COMPLETE

Inspection Date: Friday, October 08, 2004

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.a Roads: Construction, Maintenance, Surfacing		✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other	✓			

Permit Number: C0070013
Inspection Type: COMPLETE

Inspection Date: Friday, October 08, 2004 Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit expires 05/06/2006. Other documents include the following:

- -Certificate of Insurance terminates 06/01/2005.
- -UPDES permit UTG040013 expires midnight 04/30/2008, (Horse Canyon Mine).
- -UPDES permit UTG040024 expires midnight 04/30/2008, (Lila Canyon Mine).
- -Air Quality Permit DAQE-702-99.

The status of the mine site is Phase II Bond Release. The inspection frequency for this mine site is quarterly.

2. Signs and Markers

Checked the ID sign at the public accesses to the facilities area. The ID signs give the phone number of the new resident agent. The other signs and markers viewed meet the coal rules.

4.a Hydrologic Balance: Diversions

Work on the diversion channel west of the old refuse pile site is completed. The Division Hydrologist, Dave Darby, visited the site on 10/07/04 to inspect the repair work.

4.d Hydrologic Balance: Water Monitoring

Second quarter 2004 water monitoring is in the EDI website and uploaded. Third quarter 2004 water monitoring is in the EDI pipeline. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports (DMR) for June and July were reviewed during the inspection. No discharge occurred during either month.

20. Air Quality Permit

Air quality permit DAQE-702-99 was issued on August 27, 1999 and remains in effect.

Permit Number: C0070013
Inspection Type: COMPLETE

Inspection Date: Friday, October 08, 2004 Page 4 of 4

21. Bonding and Insurance

Bond number SUR004892 for \$1,137,726 was increased to \$1,253,000 on January 24, 2001. Phase II Bond Release was approved on February 12, 2003, which dropped the bond by \$191,672. The current bond is now \$1,061,328. The bond is through Lincoln General Insurance Co. This Bond is for Part A (Horse Canyon).

Bond number SB9905586 is for Part B (Lila Canyon Extension). The Bond amount is \$1,556,000 from XL Specialty Insurance. The Lila Canyon Extension has been submitted to the Division and is currently under review.

Insurance is through Federal Insurance Company policy # 37104410. The insurance was issued on 06/01/2004 and expires on 06/01/2005. Explosive coverage is noted. The minimum coverage is met and the certificate holder is listed as the State of Utah, Division of Oil, Gas and Mining.